

# ***Pro- H2o Drilling and Pump Company***

P.O. Box 5055  
Paso Robles, Ca. 93447  
Gen. Engineer/C-57 Lic. # 767541

## **Well Test Report**

**Date:** 12/24/18

**Address of test: 3520 Creston Rd. Templeton.**

<b>Time</b>	<b>H2O Cond.</b>	<b>H2O Level</b>	<b>G.P.M.</b>	<b>Comments: Static H2O Level: 213'</b>
12:30PM	Clear	213	26	Owner / test provided info below:
12:45PM	"	216.5	26	
1:00PM	"	217	26	Pump :
1:30PM	"	217	26	T.D.:
2:00PM	"	217	26	Casing Size: 5"
2:30PM	"	217	26	Prod. Tee size: 1.5"
3:00PM	"	217	26	Boosted ter size/ Make/N/A
3:30PM	"	217	26	Size press. Tank? N/A
4:00PM	"	217	26	Size Storage tank/Steel or plastic?
4:30PM	"	217	26	Owner Name: __Darrel Pester
				APN # / address of well: 033-011-026

### **Recovery:**

<b>Time</b>	<b>H2O Lev.</b>	<b>Time</b>	<b>H2O Lev.</b>	<b>Time</b>	<b>H2O Lev.</b>	<b>Comments:</b>
4:31	214	4:37	213	4:43	213	Escrow :
4:32	213	4:38	213	4:44	213	e-mail : scott@agzone.services
4:33	213	4:39	213	4:45	213	Phone Numbers: (805)591-4404
4:34	213	4:40	213			Agent: Agzone- Scott McKensie
4:35	213	4:41	213			
4:36	213	4:42	213			