


MOONRIDGE SERVICE STATION (T0607124341) - [\(MAP\)](#)
[SIGN UP FOR EMAIL ALERTS](#)

42081 BIG BEAR BOULEVARD
BIG BEAR LAKE, CA 92315
SAN BERNARDINO COUNTY
LUST [CLEANUP SITE \(INFO\)](#)

OPEN - SITE ASSESSMENT AS OF 5/2/2018 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CLEANUP OVERSIGHT AGENCIES

SANTA ANA RWQCB (REGION 8) (**LEAD**) - CASE #: 083604001T

CASEWORKER: [MIGUEL OVIEDO](#)

SAN BERNARDINO COUNTY

[Summary](#) [Case Reviews](#) [Cleanup Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - SITE ASSESSMENT AS OF 5/2/2018 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

GASOLINE

FILE LOCATION

REGIONAL BOARD

DWR GROUNDWATER SUB-BASIN NAME

Bear Valley (8-009)

POTENTIAL MEDIA OF CONCERN

AQUIFER USED FOR DRINKING WATER SUPPLY

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Bear Valley (801.71)

Site History

Environmental reports pertaining to subsurface investigations/testing and site remediation performed in conjunction with this project, as well as the Regional Board case file, should be reviewed in their entirety to obtain further details regarding this cleanup effort. Regional Board staff are not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants working for the responsible party.

[Back to Top](#)
[Conditions of Use](#)


MOONRIDGE SERVICE STATION (T0607100237) - [\(MAP\)](#)
[SIGN UP FOR EMAIL ALERTS](#)

42081 BIG BEAR BLVD
BIG BEAR LAKE, CA 92315
SAN BERNARDINO COUNTY
LUST CLEANUP SITE [\(INFO\)](#)

OPEN - SITE ASSESSMENT AS OF 5/2/2018 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CUF Claim #: 2103, 17778
CUF Priority Assigned: B
CUF Amount Paid: \$2,074,912

CLEANUP OVERSIGHT AGENCIES

SANTA ANA RWQCB (REGION 8) (**LEAD**) - CASE #: 083601904T
CASEWORKER: [MIGUEL OVIEDO](#)
SAN BERNARDINO COUNTY

[Summary](#) [Case Reviews](#) [Cleanup Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#) [LUST CUF Data](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - SITE ASSESSMENT AS OF 5/2/2018 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

GASOLINE

FILE LOCATION

REGIONAL BOARD

DWR GROUNDWATER SUB-BASIN NAME

Bear Valley (8-009)

POTENTIAL MEDIA OF CONCERN

AQUIFER USED FOR DRINKING WATER SUPPLY

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Bear Valley (801.71)

Site History

Environmental reports pertaining to subsurface investigations/testing and site remediation performed in conjunction with this project, as well as the Regional Board case file, should be reviewed in their entirety to obtain further details regarding this cleanup effort. Regional Board staff are not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants working for the responsible party.

CROSSROAD FUEL (T0607145144) - [\(MAP\)](#)
[SIGN UP FOR EMAIL ALERTS](#)

101 BIG BEAR BOULEVARD, WEST
BIG BEAR CITY, CA 92314
SAN BERNARDINO COUNTY
LUST CLEANUP SITE ([INFO](#))

OPEN - SITE ASSESSMENT AS OF 12/3/2020 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CUF Claim #: 17992
CUF Priority Assigned: B
CUF Amount Paid: \$1,494,604

CLEANUP OVERSIGHT AGENCIES

SANTA ANA RWQCB (REGION 8) (**LEAD**) - CASE #: 083604080T
CASEWORKER: [KYLE WRIGHT](#)
SAN BERNARDINO COUNTY - CASE #: 2003030

[Summary](#) [Case Reviews](#) [Cleanup Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#) [LUST CUF Data](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - SITE ASSESSMENT AS OF 12/3/2020 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

GASOLINE, MTBE / TBA / OTHER FUEL OXYGENATES, TERT-BUTYL ALCOHOL
(TBA)

FILE LOCATION

REGIONAL BOARD

DWR GROUNDWATER SUB-BASIN NAME

Bear Valley (8-009)

GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY : 7, SEMI-ANNUALLY : 8, ANNUALLY : 15, OTHER : 3

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

- Assessment Incomplete - *MtBE plume has migrated offsite proximate to large-production water supply well*
- Well Being Sampled During Remedial Action for Progress Assessment - *MtBE plume has migrated offsite proximate to large-production water supply well*
- Well Has Not Shown Reliable Consistency Yet To Warrant Reduction in Sampling Frequency - *Drastic concs fluctuations as a result of mountain snow melt/seasonal water table rises & falls*
- Well Is Last Point of Monitoring Prior to possible impact to Receptor - *MtBE plume has migrated offsite proximate to large-production water supply well*

POTENTIAL MEDIA OF CONCERN

AQUIFER USED FOR DRINKING WATER SUPPLY

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Baldwin (801.73)

Site History

Environmental reports pertaining to subsurface investigations/testing and site remediation performed in conjunction with this project, as well as the Regional Board case file, should be reviewed in their entirety to obtain further details regarding this cleanup effort. Regional Board staff are not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants working for the responsible party.


BEAR VALLEY PAVING (T0607100630) - [\(MAP\)](#)
[SIGN UP FOR EMAIL ALERTS](#)

41841 GARSTIN DRIVE
BIG BEAR LAKE, CA 92315
SAN BERNARDINO COUNTY
LUST CLEANUP SITE ([INFO](#))

OPEN - ELIGIBLE FOR CLOSURE AS OF 3/23/2021 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CLEANUP OVERSIGHT AGENCIES

SANTA ANA RWQCB (REGION 8) (**LEAD**) - CASE #: 083603641T

CASEWORKER: [KYLE WRIGHT](#)

SAN BERNARDINO COUNTY - CASE #: 99103

[Summary](#) [Case Reviews](#) [Cleanup Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - ELIGIBLE FOR CLOSURE AS OF 3/23/2021 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

GASOLINE, MTBE / TBA / OTHER FUEL OXYGENATES

FILE LOCATION

REGIONAL BOARD

DWR GROUNDWATER SUB-BASIN NAME

Bear Valley (8-009)

GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - OTHER : 5

POTENTIAL MEDIA OF CONCERN

AQUIFER USED FOR DRINKING WATER SUPPLY

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Bear Valley (801.71)

Site History

Environmental reports pertaining to subsurface investigations/testing and site remediation performed in conjunction with this project, as well as the Regional Board case file, should be reviewed in their entirety to obtain further details regarding this cleanup effort. Regional Board staff are not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants working for the responsible party.


BIG BEAR MARINA (T0607100283) - [\(MAP\)](#)
[SIGN UP FOR EMAIL ALERTS](#)

500 PAINE RD
BIG BEAR LAKE, CA 92315
SAN BERNARDINO COUNTY
LUST CLEANUP SITE [\(INFO\)](#)

OPEN - REMEDIATION AS OF 11/8/2010 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CUF Claim #: 12126
CUF Priority Assigned: B
CUF Amount Paid: \$897,120

CLEANUP OVERSIGHT AGENCIES

SANTA ANA RWQCB (REGION 8) **(LEAD)** - CASE #: 083602283T
CASEWORKER: [MIGUEL OVIEDO](#)
SAN BERNARDINO COUNTY - CASE #: 93027

[Summary](#) [Case Reviews](#) [Cleanup Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#) [LUST CUF Data](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - REMEDIATION AS OF 11/8/2010 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

GASOLINE, MTBE / TBA / OTHER FUEL OXYGENATES

FILE LOCATION

REGIONAL BOARD

DWR GROUNDWATER SUB-BASIN NAME

Bear Valley (8-009)

GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - SEMI-ANNUALLY : 5, OTHER : 1

POTENTIAL MEDIA OF CONCERN

AQUIFER USED FOR DRINKING WATER SUPPLY, SURFACE WATER

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Bear Valley (801.71)

Site History

Environmental reports pertaining to subsurface investigations/testing and site remediation performed in conjunction with this project, as well as the Regional Board case file, should be reviewed in their entirety to obtain further details regarding this cleanup effort. Regional Board staff are not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants working for the responsible party.

WAHL'S TEXACO (T0607100176) - [\(MAP\)](#)
[SIGN UP FOR EMAIL ALERTS](#)

40553 BIG BEAR BLVD
BIG BEAR LAKE, CA 92513
SAN BERNARDINO COUNTY
LUST CLEANUP SITE [\(INFO\)](#)

OPEN - ELIGIBLE FOR CLOSURE AS OF 9/19/2017 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CUF Claim #: 3226
CUF Priority Assigned: B
CUF Amount Paid: \$1,495,000

CLEANUP OVERSIGHT AGENCIES

SANTA ANA RWQCB (REGION 8) (**LEAD**) - CASE #: 083601573T
CASEWORKER: [KYLE WRIGHT](#)
SAN BERNARDINO COUNTY - CASE #: 90156

[Summary](#) [Case Reviews](#) [Cleanup Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#) [LUST CUF Data](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - ELIGIBLE FOR CLOSURE AS OF 9/19/2017 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

GASOLINE

FILE LOCATION

REGIONAL BOARD

DWR GROUNDWATER SUB-BASIN NAME

Bear Valley (8-009)

GROUNDWATER MONITORING FREQUENCY

OF WELLS MONITORED - QUARTERLY : 10, SEMI-ANNUALLY : 9, OTHER : 5

REASONS FOR QUARTERLY OR MONTHLY OR OTHER GROUNDWATER MONITORING:

- Assessment Incomplete - *access issues due to bldgs./structures*
- Well Being Sampled During Remedial Action for Progress Assessment - *Ongoing remediation/expansion under CAO 98-112*
- Well Has Not Shown Reliable Consistency Yet To Warrant Reduction in Sampling Frequency - *Drastic fluctuation in contaminat concentrations seasonally*

POTENTIAL MEDIA OF CONCERN

AQUIFER USED FOR DRINKING WATER SUPPLY

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Bear Valley (801.71)

Site History

Environmental reports pertaining to subsurface investigations/testing and site remediation performed in conjunction with this project, as well as the Regional Board case file, should be reviewed in their entirety to obtain further details regarding this cleanup effort. Regional Board staff are not responsible for the accuracy of any professional interpretations provided in reports submitted by consultants working for the responsible party.


BIG BEAR CLS III WMF (L10007155213) - ([MAP](#))
[SIGN UP FOR EMAIL ALERTS](#)

1.5 MILE OF BALDWIN LAKE
BIG BEAR, CA
SAN BERNARDINO COUNTY
LAND DISPOSAL SITE ([INFO](#))

OPEN - CLOSED/WITH MONITORING AS OF 6/20/2013 - [DEFINITION](#)

[PRINTABLE CASE SUMMARY](#) / [CSM REPORT](#)

CLEANUP OVERSIGHT AGENCIES

COLORADO RIVER BASIN RWQCB (REGION 7) (**LEAD**) - CASE #: 7A360304281

CASEWORKER: [SCOT STORMO](#)

[Summary](#) [Cleanup](#) [Action Report](#) [Regulatory Activities](#) [Environmental Data \(ESI\)](#) [Site Maps / Documents](#) [Community Involvement](#) [Related Cases](#)

Regulatory Profile
[PRINTABLE CASE SUMMARY](#)
CLEANUP STATUS - [DEFINITIONS](#)

OPEN - CLOSED/WITH MONITORING AS OF 6/20/2013 - [CLEANUP STATUS HISTORY](#)

POTENTIAL CONTAMINANTS OF CONCERN

NONE SPECIFIED

FILE LOCATION
DWR GROUNDWATER SUB-BASIN NAME
FACILITY TYPE

TITLE 27 - MUNICIPAL SOLID WASTE LANDFILL

POTENTIAL MEDIA OF CONCERN

NONE SPECIFIED

DESIGNATED GROUNDWATER BENEFICIAL USE(S) - [DEFINITIONS](#)

MUN, PROC - Note: Also incl all of 801.73.

CALWATER WATERSHED NAME

Santa Ana River - San Bernardino Mountain - Baldwin (801.73)

Site History

The Facility was originally permitted by the Regional Water Board on June 28, 1973. The types of waste that have been accepted at the BBSL include residential, commercial, demolition/construction, and agricultural. The Discharger submitted a report of waste discharge (ROWD), dated March 12, 2013, to update the WDRs for the Facility to incorporate changes resulting from the final closure of the landfill and to comply with current laws and regulations, as set forth in the California Water Code and the California Code of Regulations, Title 27. The Discharger currently operates a refuse transfer station at the Facility. The discharge or deposit of any solid waste at this site is prohibited.

[Back to Top](#)
[Conditions of Use](#)

DEPARTMENT OF TOXIC SUBSTANCES CONTROL
ENVIROSTOR



BIG BEAR AUXILIARY AIRPORT (80000973)

[SIGN UP FOR EMAIL ALERTS](#)

BIG BEAR, CA
SAN BERNARDINO COUNTY
SITE TYPE: FUDS

SUPERVISOR: [DOUGLAS BAUTISTA](#)
OFFICE: CLEANUP CYPRESS
CENSUS TRACT: 6071011300
CALENVIROSCREEN PERCENTILE SCORE: 50-55%

[Summary](#) [Sub-Areas](#) [Map](#) [Related Sites](#) [CalEnviroScreen](#)

Site Information

CLEANUP STATUS

INACTIVE - NEEDS EVALUATION AS OF 7/1/2005

SITE TYPE: FUDS

NATIONAL PRIORITIES LIST: NO

ACRES: NONE SPECIFIED

APN: NONE SPECIFIED

CLEANUP OVERSIGHT AGENCIES:

DTSC - SITE CLEANUP PROGRAM - **LEAD AGENCY**

ENVIROSTOR ID: 80000973

SITE CODE:

SPECIAL PROGRAM:

FUNDING: DERA

ASSEMBLY DISTRICT: 34

SENATE DISTRICT: 19

Regulatory Profile

PAST USE(S) THAT CAUSED CONTAMINATION

NONE SPECIFIED

POTENTIAL CONTAMINANTS OF CONCERN

NONE SPECIFIED

POTENTIAL MEDIA AFFECTED

NONE SPECIFIED

Site History

[Back to Top](#)

[Help](#)