

Appendix F

Native Oak Tree Inventory (Removal with Mitigation Required)

Tree #	Common Name	Scientific Name	DBH (Inches)	Canopy Radius (Feet)	Health/Structure Condition	Action	Mitigation
1	Blue Oak	<i>Quercus douglasii</i>	22"	15 ft.	2.5 (Fair); Unbalanced crown	Proposed for Removal	22"
9	Blue Oak	<i>Quercus douglasii</i>	16"	20ft.	2(Fair); Significant epicormic growth	Proposed for Removal	16"
11	Valley Oak	<i>Quercus lobata</i>	23"	20ft.	2.5(Fair); Narrow crown	Proposed for Removal	23"
12	Blue Oak	<i>Quercus douglasii</i>	16"/16"	20ft.	2(Fair); Unbalanced crown	Proposed for Removal	32"
13	Blue Oak	<i>Quercus douglasii</i>	18"	20ft.	2.5(Fair); Limited canopy	Proposed for Removal	18"
14	Blue Oak	<i>Quercus douglasii</i>	26"	30ft.	2(Fair); Large dead limbs	Proposed for Removal	26"
17	Blue Oak	<i>Quercus douglasii</i>	8"	10ft.	2(Fair); Narrow canopy	Proposed for Removal	8"
19	Blue Oak	<i>Quercus douglasii</i>	22"	20ft.	2(Fair); Dead limbs	Proposed for Removal	22"
21	Blue Oak	<i>Quercus douglasii</i>	14"/11"	15ft.	3(Good); Thin canopy	Proposed for Removal	25"
22	Blue Oak	<i>Quercus douglasii</i>	17"	20ft.	3(Good); Thin canopy	Proposed for Removal	17"
25	Blue Oak	<i>Quercus douglasii</i>	26"	25ft.	3(Good); Possible longitudinal crack	Proposed for Removal	26"
28	Blue Oak	<i>Quercus douglasii</i>	13"	10ft.	2(Fair); Narrow canopy	Proposed for Removal	13"
29	Blue Oak	<i>Quercus douglasii</i>	20"	20ft.	3(Good); Epicormic growth along stem	Proposed for Removal	20"
30	Live Oak	<i>Quercus wislenzii</i>	5"/7"	20ft.	3(Good); Slight lean	Proposed for Removal	12"
35	Blue Oak	<i>Quercus douglasii</i>	13"	15ft.	2(Fair); Excavation at root zone	Proposed for Removal	13"
38	Blue Oak	<i>Quercus douglasii</i>	11"/12"	15ft.	2(Fair); Inclusion in lower stem	Proposed for Removal	23"
39	Blue Oak	<i>Quercus douglasii</i>	16"	15ft.	3(Good); Active closure of small injuries along stem	Proposed for Removal	16"

Tree #	Common Name	Scientific Name	DBH (Inches)	Canopy Radius (Feet)	Health/Structure Condition	Action	Mitigation
40	Blue Oak	<i>Quercus douglasii</i>	8"	10ft.	2(Fair); Unbalanced crown	Proposed for Removal	8"
41	Blue Oak	<i>Quercus douglasii</i>	10"	10ft.	2(Fair); Unbalanced crown	Proposed for Removal	10"
43	Blue Oak	<i>Quercus douglasii</i>	12"	15ft.	3(Good); Balanced crown with slight lean to west	Proposed for Removal	12"
44	Blue Oak	<i>Quercus douglasii</i>	15"/8"	10ft.	2(Fair); Balanced crown	Proposed for Removal	23"
45	Blue Oak	<i>Quercus douglasii</i>	8"	10ft.	2(Fair); Unbalanced crown	Proposed for Removal	8"
47	Blue Oak	<i>Quercus douglasii</i>	13"	15ft.	3(Good); Thin canopy	Proposed for Removal	13"
48	Blue Oak	<i>Quercus douglasii</i>	14"	15ft.	2.5(Fair); Unbalanced crown	Proposed for Removal	14"
49	Blue Oak	<i>Quercus douglasii</i>	11"	10ft.	2.5(Fair); Unbalanced crown	Proposed for Removal	11"
53	Blue Oak	<i>Quercus douglasii</i>	14"	15ft.	2(Fair); Injury closures on lower stem	Proposed for Removal	14"
55	Blue Oak	<i>Quercus douglasii</i>	13"	15ft.	2(Fair); Unbalanced crown	Proposed for Removal	13"
57	Blue Oak	<i>Quercus douglasii</i>	15"/15"	25ft.	2.5(Fair); Inclusion in lower stem	Proposed for Removal	30"
89	Blue Oak	<i>Quercus douglasii</i>	23"	20ft.	4 (Excellent)	Proposed for Removal	23"
90	Blue Oak	<i>Quercus douglasii</i>	20"	20ft.	3.5 (Good); Slightly unbalanced crown	Proposed for Removal	20"
91	Valley Oak	<i>Quercus lobata</i>	6"	8ft.	2.5 (Fair); Epicormic growth	Proposed for Removal	6"
Total Inches removed requiring mitigation							537 Inches